

Natural Gas Detector



— Confined Space Monitoring



— Leak Investigation



— Bar Hole Sampling



— Line Purge Testing

1 Monitor
4 Functions



Actual Size

GX-2012



Ordering Info & Accessories

Part Number	Description
72-0290-01-A	GX-2012, 1 sensor, LEL base with alkaline battery pack
72-0290-02-A	GX-2012, 1 sensor, O2 base with alkaline battery pack
72-0290-03-A	GX-2012, 1 sensor, H2S base with alkaline battery pack
72-0290-04-A	GX-2012, 1 sensor, CO base with alkaline battery pack
72-0290-08-A	GX-2012, 2 sensor, LEL / O2 base with alkaline battery pack
72-0290-09-A	GX-2012, 2 sensor, LEL / H2S base with alkaline battery pack
72-0290-10-A	GX-2012, 2 sensor, LEL / CO base with alkaline battery pack
72-0290-12-A	GX-2012, 2 sensor, O2 / CO base with alkaline battery pack
72-0290-16-A	GX-2012, 3 sensor, LEL / O2 / H2S base with alkaline battery pack
72-0290-17-A	GX-2012, 3 sensor, LEL / O2 / CO base with alkaline battery pack
72-0290-18-A	GX-2012, 3 sensor, LEL / % volume CH4 / O2 base with alkaline battery pack
72-0290-22-A	GX-2012, 4 sensor, LEL / O2 / H2S / CO with alkaline battery pack
72-0290-23-A	GX-2012, 4 sensor, LEL / % volume CH4 / O2 / CO base with alkaline battery pack
72-0290-23-A	GX-2012, 4 sensor, LEL / % volume CH4 / O2 / H2S base with alkaline battery pack
72-0290-23-A	GX-2012, 5 sensor, LEL / % volume CH4 / O2 / H2S / CO base with alkaline battery pack

Note: Replace "A" with "C" if you want to purchase the Li-Ion Battery Pack and 100 - 240 VAC charger



Calibration Kits



Bar Hole Probe



Confined Space Kit

SDM-2012 Calibration Stations

- Stand-alone station (no PC Required)
- Charging
- Calibration
- Bump Test
- Save Bump Test and Calibration records



Charging Cradle