

Pro Form Products Ltd. 604 McGeachie Drive Milton, Ontario, L9T 3Y5 Canada 905-878-4990

PRODUCT: 12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4

Mixture

SECTION 01: IDENTIFICATION

12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4 Product identifier.....

Paint related materials.

Other means of identification

Chemical family...... Recommended use and restrictions on ...

Pro Form Products Ltd.

Initial supplier identifier..... 604 McGeachie Drive

Milton, Ontario L9T3Y5 Tel (905) 878-4990 Fax (905) 878-1189

24 hour emergency number:....

For transportation emergencies (in Canada) call CANUTEC 1-888-226-8832 (CAN-UTEC);

IN THE UNITED STATES CALL CHEMTRÉC 1-800-424-9300. ** For medical emergencies contact your local poison control centre **.

NFPA rating...... Health: 2 Fire: 4 Reactivity: 0.

HMIS...... H: 2 F:4 R: 0.

SECTION 02: HAZARD IDENTIFICATION



Flammable Liquid 2. Skin Corrosion/Irritation — Category 2. Sensitization - Skin — Category 1. Serious Eye Damage/Eye Irritation — Category 2A. Specific Target Organ Toxicity — Single Exposure — Category 3. (CNS). Reproductive Toxicity — Category 2. Carcinogenicity — Category 2. Aquatic Acute 1. Aquatic Chronic 1. Hazard Classification..... DANGER. Signal Word..... H225 Highly flammable liquid and vapour. H315 Causes skin irritation. H317 May cause an Hazard Description..... allergic skin reaction. H319 Causes serious eye irritation. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. H351 This product contains ingredients that are suspected of causing cancer. H361 Suspected of damaging fertility or the unborn child. H400 Very toxic to aquatic life. H410 Very toxic to aquatic life with long lasting effects P201 Obtain special instructions before use. P202 Do not handle this product until all Prevention..... safety instructions have been read and understood. P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233 Keep container tightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P272 Contaminated work clothing should not be allowed out of the workplace. P273 Avoid release to the environment. P271 Use only outdoors or in a well ventilated area. P280 Wear protective gloves and eye protection. P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use Response safety shower . P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P308 + P313 If exposed or concerned, get medical advice/attention. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P332 + P313 - If skin irritation occurs get medical attention or advice. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. P391 Collect spillage P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep cool. Storage..... P405 Store locked up. P501 Dispose all unused, waste or empty containers in accordance with local regulations. Disposal..... Other hazards..... None known. Note This product mixture has been classified based on its ingredients.



PRODUCT: 12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4

SECTION 03: COMPOSITION / INFORMATION ON INGREDIENTS		
CHEMICAL NAME AND SYNONYMS	CAS#	WT. %
4-Chlorobenzotrifluoride	98-56-6	30-60
Acetone	67-64-1	10-30
n-Butyl Acetate	123-86-4	10-30
Decanedioic acid, methyl 1,2,2,6,6-pentamethyl-4-piperidinyl ester	82919-37-7	0.1-1
Bis (1,2,2,6,6- Pentamethyl-4- Piperidyl) Sebacate	41556-26-7	0.1-1
C7-C9 Branched Alkyl Esters	127519-17-9	0.1-1
<< The actual concentration(s) withheld as a trade secret>>	> .	

SECTION 04: FIRST-AID MEASURES

Flush affected area with water for at least 15 minutes. Remove contaminated clothing and Skin contact..... launder before reuse. If irritation persists, seek medical attention. Eye contact..... In case of contact, immediately flush eyes, keeping eyelids open, with plenty of water for at least 15 minutes. Remove contact lenses if safe to do so. Obtain medical attention. If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is Inhalation..... difficult, give oxygen, obtain medical attention. Do not induce vomiting. Rinse mouth with plenty of water. If spontaneous vomiting occurs Ingestion..... have victim lean forward with head down to prevent aspiration of fluid into the lungs. Never give anything by mouth to an unconscious person. If symptoms persist, immediately obtain medical help. May cause respiratory irritation. Can cause skin sensitization. Causes skin and eye Most important symptoms and effects, whether acute or delayed irritation. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. Direct contact with eyes may cause temporary irritation. Indication of immediate medical attention Treat symptomatically. and special treatment needed, if necessary

> In the event of an incident involving this product ensure that medical authorities are provided a copy of this safety data sheet.

SECTION 05: FIRE-FIGHTING MEASURES

Suitable extinguishing media..... Unsuitable extinguishing media..... Specific hazards arising from the hazardous product, such as the nature of any hazardous combustion products Special protective equipment and precautions for fire-fighters

Additional information.....

"Alcohol" foam, CO2, dry chemical. Water spray. Do not use solid water streams or water jet.

Extremely flammable. Hazardous combustion products may include but not limited to:. Oxides of carbon (CO, CO2).

Firefighter should be equipped with self-contained breathing apparatus and full protective clothing to protect against potentially toxic and irritating fumes. Use water spray to cool containers. Do not allow run-off into drains, surface waters or ground waters.

SECTION 06: ACCIDENTAL RELEASE MEASURES

and emergency procedures

Personal precautions, protective equipment No action shall be taken involving any personal risk or without suitable training. Avoid breathing vapours. Evacuate personnel to a safe area. Ensure adequate ventilation. Remove all sources of ignition. Beware of vapours accumulating to form explosive concentrations. Vapours can accumulate in low areas. Wear appropriate personal protection equipment.

Environmental precautions.....

Do not allow product to leak into drains or waterways. If spill does contaminate waterways

Methods and materials for containment . and cleaning up

then inform authorities. Contain spilled material and then collect with non-combustible absorbent material, (e.g. sand, earth, diatomaceous earth, vermiculite) and place in container for disposal according to local/national regulations.

SECTION 07: HANDLING AND STORAGE

Precautions for safe handling.....

Extremely flammable. Avoid formation of aerosol. Do not spray on a naked flame or any incandescent material. Obtain special instructions before use. No smoking. Use in well ventilated areas. Keep away from heat, sparks, and open flame. Ground handling equipment. Prevent accumulation of electrostatic charges. Always adopt precautionary measures against build-up of static which may arise from appliances, handling and the containers in which product is packed. Avoid all skin contact and ventilate adequately, otherwise wear an appropriate breathing apparatus. Avoid breathing vapours or mist. Handle and open container with care. Dispose of rinse water according to local, Provincial and Federal guidelines. Employees should wash hands and face before eating or drinking. Handle in accordance with good industrial hygiene and safety practices.



PRODUCT: 12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4

SECTION 07: HANDLING AND STORAGE

Conditions for safe storage, including any incompatibilities

Keep away from heat, sparks, and open flames. Keep container closed when not in use. Use explosion proof equipment in areas where vapour concentrations can become ignitable. Store away from oxidizing and reducing materials. Store away from sunlight. Store in a cool and dry place, for product integrity. Do not cut, grind or weld on or near container, do not expose containers to heat, flame, sparks, static electricity, or other sources of ignition: the containers may explode and cause injury or death. Precautions should generally be taken against electrostatic charges according to the equipment used and the way the product is handled and packaged. Avoid sources of ignition. Electrical installations / working materials must comply with the technological safety standards. Incompatible materials include, but not limited to:. Strong oxidizing agents. Bases. Plastics. Rubber. Amines. Reducing agents. Strong bases. Oxidizing agents.

SECTION 08: EXPOSURE CONTROLS / PERSONAL PROTECTION

INGREDIENTS	TWA AC	GIH TLV STEL	OSH. PEL	A PEL STEL	NIOSH REL
4-Chlorobenzotrifluoride Acetone	Not established 250 ppm TLV	Not established 500 ppm	Not established 1,000 ppm	Not established Not established	Not established 250 ppm
n-Butyl Acetate	50 ppm	om (TWA); 750ppm (STEL 150 ppm	-) 150 ppm	200 ppm	150 ppm / STEL 200 ppm
	CA ON: 50ppm (T	WA), 150ppm (STEL)			
Decanedioic acid, methyl 1,2,2,6,6-pentamethyl-4-piperidinyl ester	Not Established	Not Established	Not Established	Not Established	Not Established
Bis (1,2,2,6,6- Pentamethyl-4- Piperidyl) Sebacate	Not established	Not established	Not established	Not established	Not established
C7-C9 Branched Alkyl Esters	Not established	Not established	Not established	Not established	Not established
Appropriate engineering Personal Protective Equ	ipment	Use local exhaust or gene Explosion-proof exhaust	ventilation.	·	·
Gloves/ type		Wear skin protection equithe nature of the work to supplier for additional rec Liquid chemical goggles. exists. Consult your personal transfer of the supplier for additional recurrence of the suppli	be performed. Consult ommendations. Chemical safety gogg	your personal protectives and full faceshield if	e equipment a splash hazard
Respiratory/type		recommendations. Wear an appropriate, pro recommended exposure additional recommendation	perly fitted respirator v limits. Consult your pe	vhen contaminant levels	s exceed the
Clothing/type		Wear chemical resistant of	clothing. Consult your	personal protective equ	ipment supplier for
Footwear/type		additional recommendation Wear chemical resistant of additional recommendational recommendational recommendation and additional recommendation and additiona	safety boots. Consult y	our personal protective	equipment supplier
Other/type		Emergency showers and their hands and face before	eye wash stations sho		

SECTION 09: PHYSICAL AND CHEMICAL PROPERTIES

Appearance/Physical state	Liquid.
Colour	Colourless.
Odour	Aromatic.
Odour threshold (ppm)	Not available.
pH	Not available.
Melting / Freezing point (deg C)Initial boiling point / boiling range (deg C).	Not available.
Initial boiling point / boiling range (deg C).	Not available.
Flash point (deg C), method	-20°C .
Evaporation rate	Not available.
Flammability (solids and gases)	Flammable liquid.
Flammability (solids and gases) Upper flammable limit (% vol)	Not available.
Lower flammable limit (% vol)	Not available.
Vapour pressure (mm Hg)	Not available.
Vapour density (air=1)	Not available.



PRODUCT: 12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4

SECTION 09: PHYSICAL AND CHEMICAL PROPERTIES

Relative Density (Specific Gravity)	1.106. Not available. Not available. Not available.
Decomposition temperatureViscosity	Not available. Not available.
% Volume Volatile exemptFormula LBS/GAL	54.87. 9.23.
% Weight Solids % Volume Solids	30.89. 28.87.
% Weight Volatile (VOC)	12.62.
% Volume Volatile (VOC) LBS VOC/GAL solids	16.24. 4.0.
Total MIR Coverage (sq ft/gal @ 1 mil)	0.20. 463.
VOC LBS/GAL less exempt volatiles VOC LBS/GAL less water	2.58. 1.16.
Percent weight binder	30.2.
Percent volume binder Percent weight catalyst	28.2. 0.10.
Percent volume catalyst Eq.Wt.OH	0.11. 1784.29.

SECTION 10: STABILITY AND REACTIVITY

Avoid heat, sparks and flames. Reactivity Chemical stability..... Stable at normal temperatures and pressures. Possibility of hazardous reactions..... Will not occur under normal temperature and pressure. Vapours may form explosive mixture with air. Conditions to avoid, including static Avoid heat, spark, open flames. Do not pressurize, cut, weld, braze, solder, drill, grind or discharge, shock or vibration expose containers to heat or sources of ignition. Avoid electrostatic discharge. Incompatible materails..... Strong oxidizing agents. Bases. Plastics. Rubber. Amines. Oxidizing agents. Strong bases. Reducing agents.

Carbon dioxide. Carbon monoxide. Hazardous decomposition products......

SECTION 11: TOXICOLOGICAL INFORMATION

INGREDIENTS	LC50	LD50
4-Chlorobenzotrifluoride	4479 ppm	>6,800 mg/kg (rat oral); >2,700 mg/kg (rabbit dermal)
Acetone	50,100 mg/m3 8 hours, rat	5,800 mg/kg (rat oral)
n-Butyl Acetate	>33 mg/L vapour, 5.2 mg/L (rat) dust/mist	10760 mg/kg (rat, oral) 14112 mg/kg (rabbit, dermal)
Decanedioic acid, methyl 1,2,2,6,6-pentamethyl-4-piperidinyl ester	Not Available	3,230 mg/kg rat, oral
Bis (1,2,2,6,6- Pentamethyl-4- Piperidyl) Sebacate	Not Available	2369-3920 mg/kg (oral rat), >2000 mg/kg (dermal rabbit)
C7-C9 Branched Alkyl Esters	Not Available	>2,000 mg/kg oral rat >2,000 mg/kg dermal rat

Route of exposure......Symptoms related to the physical, chemical and toxicological characteristics

Eye contact. Skin contact. Inhalation. Ingestion.

Effects of acute exposure..... Causes serious eye irritation. Causes skin irritation. High concentrations may cause central nervous system depression such as drowsiness, headache, dizziness, vertigo, nausea and fatique.

Skin corrosion\irritation..... Causes skin irritation. Causes serious eye irritation. Serious eye damage/eye irritation.....

Respiratory Sensitization..... Not expected to be a respiratory sensitizer.

Skin Sensitization..... May cause an allergic skin reaction.

Carcinogenicity..... No component of this product present at levels greater than or equal to 0.1% is identified

as probable, possible or confirmed human carcinogen by IARC or ACGIH.

Reproductive effects..... Suspected of damaging fertility or the unborn child.

STOT-SE....STOT-RE..... Central nervous system.

Not classified.

Does not meet the criteria for this classification. Aspiration Hazard.....

PRODUCT: 12522 CLEARCOAT KIT CONTAINS 12370, 12376 & PB 3001-4

SECTION 12: ECOLOGICAL INFORMATION

Do not allow product to enter drains, sewers, bodies of water or soil. Ecotoxicity.....

Bioaccumulative potential..... Not available as a product. Mobility in soil.....Persistence and degradability..... Not available as a product. Not available as a product.

SECTION 13: DISPOSAL CONSIDERATIONS

Information on safe handling for disposal. and methods of disposal, including any contaminated packaging

Dispose of waste in accordance with all applicable Federal, Provincial/State and local regulations. Empty containers must be handled with care due to product residue.

SECTION 14: TRANSPORT INFORMATION

UN1263 - PAINT - Class 3 - Packing Group II - This product meets limited quantity TDG Classification..... exemption when shipped in containers less than 5 litres. UN1263 - PAINT - Class 3 - Packing Group II - Ltd Qty (5 Liter). DOT Classification (Road)..... Refer to 49CRF 172.101 for additional non-bulk packaging requirements. UN1263 - PAINT - Class 3 - Packing Group II. Limited Quantity. Do not ship by air without IATA Classification (Air)..... checking appropriate IATA regulations.
UN1263 - PAINT - Class 3 - Packing Group II - EmS: F-E S-E. Limited Quantity. Check IMDG Classification (Marine)..... IMDG regulations for limited quantity exemptions. Marine Pollutant..... Proof of Classification..... In accordance with Part 2.2.1 of the Transportation of Dangerous Goods Regulations (July

SECTION 15: REGULATORY INFORMATION

CEPA status..... On Domestic Substances List (DSL).

National Pollutant Release Inventory (NPRI) Environmental Emergency Regulations.... Some components of this product are on the Environmental Emergency Regulations and

may require additional reporting. Bis (1,2,2,6,6- Pentamethyl-4- Piperidyl) Sebacate (CAS #

41556-26-7) Part 1. Categorization of the DSL.....

Some components met the criteria under subsection 73(1) of CEPA during categorization

of the DSL. Please check to see if this affects your company. (CAS # 67-64-1). (CAS #

41556-26-7)

All components are either listed or exempt from the TSCA. . TSCA inventory status.....

OSHA..... This product is considered hazardous under the OSHA Hazard Communication Standard.

SARA Title III

Section 302 - extremely hazardous None.

substances

Section 311/312 - hazard categories....... Immediate health, delayed health, fire hazard.

Section 313..... None. EPA hazardous air pollutants (HAPS) None. 40CFR63

California Proposition 65..... *WARNING: This product contains a chemical known to the State of California to cause

cancer. (4-Chlorobenzotrifluoride). For more information, go to

2, 2014) - we certify that classification of this product is correct. .

www.P65Warnings.ca.gov.

SECTION 16: OTHER INFORMATION

REGULATORY AFFAIRS. Prepared by:

(800) 387-7981. Telephone number:..... Disclaimer:....

DISCLAIMER: All information appearing herein is based upon data obtained from experience and recognized technical sources. To the best of our knowledge, it is believed to be correct as of the date of issue but we make no representations as to its accuracy or sufficiency and do not suggest or guarantee that any hazards listed herein are the only ones which exist. The hazard information contained herein is offered solely for the consideration of the user, subject to his own investigation and verification of compliance with applicable regulations, including the safe use of the product under every foreseeable condition. The information relates only to the product designated herein, and does not

relate to its use in combination with any other material or in any other process.

Date of the latest revision of the safety ... 2024-10-08

data sheet





Pro Form Products Ltd. 604 McGeachie Drive Milton, Ontario, L9T 3Y5 Canada 905-878-4990

12376 FAST ACTIVATOR FOR 12370 PRODUCT:

SECTION 01: IDENTIFICATION

Paints. Accelerator and activator.

Product identifier..... 12376 FAST ACTIVATOR FOR 12370

Mixture.

Other means of identification

Initial supplier identifier.....

Pro Form Products Ltd.

604 McGeachie Drive

Milton, Ontario L9T3Y5 Tel (905) 878-4990 Fax (905) 878-1189

For transportation emergencies (in Canada) call CANUTEC 1-888-226-8832 (CAN-UTEC); IN THE UNITED STATES CALL CHEMTREC 1-800-424-9300. 24 hour emergency number:.....

** For medical emergencies contact your local poison control centre **.

NFPA rating...... Health: 2 Fire: 4 Reactivity: 1.

HMIS...... H: 2 F: 4 R: 1.

SECTION 02: HAZARD IDENTIFICATION



Category 1. Eye Damage/Irritation — Category 2Â, Âcute Toxicity (Inhalation) — Ĉategory 3. Specific Target Organ Toxicity — Single Exposure — Category 3. (Respiratory system). (Narcotic Effects). (CNS). DANGER. Hazard Description. H225 Highly flammable liquid and vapour. H317 May cause an allergic skin reaction. H319 Causes serious eye irritation. H331 Toxic if inhaled. H334 May cause allergy or asthma symptoms or breathing difficulties if inhaled. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. Prevention. P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233 Keep container tightly closed. P240 Fround and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P331 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTRE or doctor. P312 Call a POISON CENTRE for perioning respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage. P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep co	Hazard Classification	Flammable Liquid 2. Sensitization - Skin — Category 1. Sensitization - Respiratory —
3. Specific Taïget Organ Toxicity — Single Exposure — Category 3. (Respiratory system). (Narcotic Effects). (CNS). Signal Word		
(Narcotic Effects). (CÑS). DANGER. Hazard Description		
Signal Word. Hazard Description. H225 Highly flammable liquid and vapour. H317 May cause an allergic skin reaction. H319 Causes serious eye irritation. H331 Toxic if inhaled. H334 May cause allergy or asthma symptoms or breathing difficulties if inhaled. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. Prevention. Prevention. P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233 Keep container tightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage. P403+P433+P435 Store in a well ventilated area. Keep contain		
Hazard Description. H225 Highly flammable liquid and vapour. H317 May cause an allergic skin reaction. H319 Causes serious eye irritation. H331 Toxic if inhaled. H334 May cause allergy or asthma symptoms or breathing difficulties if inhaled. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. Prevention. P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233 Keep container tightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTRE/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage. P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep coo	Signal Word	
Causes serious eye irritation. H331 Toxic if inhaled. H334 May cause allergy or asthma symptoms or breathing difficulties if inhaled. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. Prevention.		
symptoms or breathing difficulties if inhaled. H335 May cause respiratory irritation. H336 May cause drowsiness or dizziness. Pervention	Hazard Description	
May cause drowsiness or dizziness. P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233 Keep container tightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTRE/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep cool. P405 Store locked up. Disposal P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep cool. P405 Store locked up.		
Prevention		
Keep container fightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage P403+P433+P435 Store in a well ventilated area. Keep container tightly closed. Keep cool. P405 Store locked up. Disposal P501 Dispose all unused, waste or empty containers in accordance with local regulations. None known.		May cause drowsiness or dizziness.
Keep container tightly closed. P240 Ground and bond container and receiving equipment. P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage	Prevention	P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233
P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower . P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		Keep container tightly closed. P240 Ground and bond container and receiving equipment.
precautionary measures against static discharge. P261 Avoid breathing mists, vapours and sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response		
sprays. P264 Wash thoroughly after handling. P271 Use only outdoors or in a well ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response		
ventilated area. P272 Contaminated work clothing should not be allowed out of the workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. Response		sprays P264 Wash thoroughly after handling P271 Use only outdoors or in a well
workplace. P280 Wear protective gloves and eye protection. P284 In case of inadequate ventilation wear respiratory protection. P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower . P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		ventilated area P272 Contaminated work clothing should not be allowed out of the
ventilation wear respiratory protection. P302 + P352 - If on skin: wash with plenty of water. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		workplace P280 Wear protective gloves and even protection P284 In case of inadequate
Response		
hair: take off all contaminated clothing immediately. Rinse thoroughly with water and use safety shower. P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage	Dognanas	
safety shower . P304 + P340 - If inhaled remove person to fresh air and keep comfortable for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage	Response	
for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		
minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		safety shower . P304 + P340 - If innaled remove person to fresh air and keep comfortable
help arrives. P311 Call a POISON CENTRE or doctor. P312 Call a POISON CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		for breathing. P305 + P351 + P338 If in eyes rinse cautiously with water for several
CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS. P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		minutes. Remove contact lenses, if present and easy to do. Continue rinsing until medical
P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		
eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		CENTER/doctor if you feel unwell. P321 - For specific treatment see section 4 on this SDS.
eye irritation persists get medical attention. P342 + P311 If experiencing respiratory symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		P333 + P313 If skin irritation or rash occurs, get medical advice/attention. P337 + P313 - If
symptoms; call poison center or doctor. P362 + P364 - Take off contaminated clothing and wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		
wash before reuse. P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. Storage		symptoms: call poison center or doctor, P362 + P364 - Take off contaminated clothing and
extinguish. Storage		
Storage		
P405 Store locked up. Disposal	Storage	
Disposal	Storage	
Other hazards None known.	Diamagal	P403 Storie locked up.
	Disposal	None bispose all unused, waste or empty containers in accordance with local regulations.
Notel nis product mixture has been classified based on its ingredients.		
	Note	ins product mixture has been classified based on its ingredients.

PRODUCT: 12376 FAST ACTIVATOR FOR 12370

SECTION 03: COMPOSITION / INFORMATION ON INGREDIENTS			
CHEMICAL NAME AND SYNONYMS	CAS#	WT. %	
Homopolymer of HDI	28182-81-2	30-60	
tert-Butyl acetate	540-88-5	30-60	
Acetic acid, methyl ester	79-20-9	1-5	
< <the a<="" actual="" as="" concentration(s)="" td="" withheld=""><td>trade secret>> .</td><td></td><td></td></the>	trade secret>> .		

SECTION 04: FIRST-AID MEASURES

Inhalation	Move to fresh air. Make victim comfortable for breathing. If breathing is difficult, give oxygen. Do not use mouth to mouth resuscitation if victim ingested or inhaled the product.
Ingestion	Obtain immediate medical attention. Do not induce vomiting. Rinse mouth with water. If spontaneous vomiting occurs have victim lean forward with head down to prevent aspiration of fluid into the lungs. Never give
Skin contact	anything by mouth to an unconscious person. Get medical attention if symptoms occur. Immediately remove all contaminated clothing, flush skin with water for at least 15 minutes. Wash clothing before reuse. If irritation persists, seek medical attention.
Eye contact	In case of contact, immediately flush eyes, keeping eyelids open, with plenty of water for at least 15 minutes. Check for and remove any contact lenses, if safe and easy to do so. Obtain medical attention.
Most important symptoms and effects, whether acute or delayed	
Additional information	In all cases, if irritation persists seek medical attention. In the event of an incident involving this product ensure that medical authorities are provided a copy of this safety data sheet.

SECTION 05: FIRE-FIGHTING MEASURES

Suitable extinguishing media..... hazardous product, such as the nature of any hazardous combustion products Special protective equipment and precautions for fire-fighters

"Alcohol" foam, CO2, dry chemical. Do not use solid water streams or water jet. During fire, gases hazardous to health may be formed.

Firefighter should be equipped with self-contained breathing apparatus and full protective clothing to protect against potentially toxic and irritating fumes. Solvent vapours may be heavier than air and may build up and travel along the ground to an ignition source, which may result in a flash back to the source of the vapours. Cool fire-exposed containers with cold water spray. Heat will cause pressure buildup and may cause explosive rupture. Do not allow run-off into drains, surface waters or ground waters.

SECTION 06: ACCIDENTAL RELEASE MEASURES

Environmental precautions.....

Do not allow product to leak into drains or waterways. If spill does contaminate waterways then inform authorities.

and emergency procedures

Personal precautions, protective equipment No action shall be taken involving any personal risk or without suitable training. Take precautions against static discharge. Equipment should be grounded. Use non-sparking tools and equipment to pick up the spilled material. Isolate area and keep unauthorized people away. Do not walk through spilled material. Wear recommended protective equipment. Ventilate. Open windows and doors to allow air circulation. Dike area to prevent spreading. The use of absorbent socks or spill pillows may be required. Stop leak if safe to do so. Prevent runoff into drains, sewers, and other waterways. Beware of vapours accumulating to form explosive concentrations. Vapors can form explosive mixture in air

Methods and materials for containment and cleaning up

Wear proper personal protection equipment. Contain spilled material and then collect with non-combustible absorbent material, (e.g. sand, earth, diatomaceous earth, vermiculite) and place in container for disposal according to local/national regulations. Treat original container as hazardous due to any residual product still in container.

SECTION 07: HANDLING AND STORAGE

Precautions for safe handling.....

Ensure that equipment is properly bonded and grounded during filling and transferring as product may become electrostatically charged. Use adequate ventilation. Do not breathe vapours, mist or dust. Wear respiratory protection if material is heated, sprayed, used in confined space, or if exposure limit is exceeded. Individuals with lung or breathing problems or prior allergic reactions to isocyanates must not be exposed vapour of spray



PRODUCT: 12376 FAST ACTIVATOR FOR 12370

SECTION 07: HANDLING AND STORAGE

Precautions for safe handling.....

mist. Avoid skin and eye contact. Avoid formation of aerosol. Do not spray on a naked flame or any incandescent material. Employees should wash hands and face before eating or drinking. Smoking, eating and drinking should be prohibited in the application area. Wash thoroughly after handling.

Conditions for safe storage, including any incompatibilities

Keep away from heat, sparks, and open flames. Exposure to vapours of heated isocyanates can be extremely dangerous. Store in tightly closed containers to prevent moisture contamination. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Provide adequate ventilation to protect from these hazards and to keep below maximum exposure values. Electrical installations / working materials must comply with the technological safety standards. Incompatible materials include, but not limited to:. Acids. Bases. Nitrates. Plastics. Strong oxidizing agents.

SECTION 08: EXPOSURE CONTROLS / PERSONAL PROTECTION

INGREDIENTS	TWA	CGIH TLV STEL	OSI PEL	HA PEL STEL	NIOSH REL
Homopolymer of HDI	5 mg/m3	Not established	5 mg/m3	Not established	5 mg/m3
	Supplier: 0.5 mg/	m3 (TWA)			
tert-Butyl acetate	200 ppm	Not established	200 ppm	Not established	200 ppm
	CA ON AB BC: 5	0ppm (TWA), 200ppm (ST	EL)		
Acetic acid, methyl ester	200 ppm	Not established	200 ppm	Not established	Not established
	CA ON: 200ppm	(TWA), 250ppm (STEV-C)			
Appropriate engineering	controls	Explosion-proof exhaust value the exposure limits.	entilation. Local exh	aust should be used to n	naintain levels below
Personal Protective Equ	ipment	and expedence minutes			
Respiratory/type		Wear an appropriate, proprecommended exposure	imits. Full Face Mas	k with organic vapor cartı	ridge, Type A filter.
Eye/type		Consult your personal pro Chemical safety goggles a personal protective equip	and full faceshield if	a splash hazard exists. C	Consult your
Gloves/ type		Impervious gloves. Consurecommendations.			
Clothing/type		Wear impervious protective for additional recommendations.	ve clothing. Consult	our personal protective	equipment supplier
Footwear/type			afety boots. Consult	your personal protective	equipment supplier
Other/type			eye wash stations sh		

SECTION 09: PHYSICAL AND CHEMICAL PROPERTIES

Appearance/Physical state	Liquid.
Colour	Not available.
Odour	Not available.
Odour threshold (ppm)	Not available.
pHHq	Not applicable.
Melting / Freezing point (deg C)	Not available.
Initial boiling point / boiling range (deg C).	Not available.
Flash point (deg C), method	Not available.
Evaporation rate	Not available.
Flammability (solids and gases)	Not applicable. Flammable liquid.
Upper flammable limit (% vol)	Not available.
Lower flammable limit (% vol)	Not available.
Vapour pressure (mm Hg)	Not available.
Vapour density (air=1)	Not available.
Relative Density (Specific Gravity)	0.997.
Solubility	Not available.
Partition coefficient — n-octanol/water	Not available.
Auto ignition temperature (deg C)	Not available.
Decomposition temperature	Not available.
Viscosity	Not available.
% Volume Volatile exempt	57.07.
% Weight Solids	50.00.
% Volume Solids	42.96.
% Weight Volatile (VOC)	0.00.
% Volume Volatile (VOC)	51.70.



PRODUCT: 12376 FAST ACTIVATOR FOR 12370

SECTION 09: PHYSICAL AND CHEMICAL PROPERTIES

Total MIR	
Coverage (sq ft/gal @ 1 mil)	689.
VOC LBS/GAL less exempt volatiles	0.00.
VOC LBS/GAL less water	0.00.
Percent weight binder	50.00.
Percent volume binder	
Eg. WT. NCO	390.00

SECTION 10: STABILITY AND REACTIVITY

Reactivity	Keep away from sparks or open flame.
Chemical stability	Stable at normal temperatures and pressures.
Possibility of hazardous reactions	Vapours may form explosive mixture with air.
Conditions to avoid, including static	Avoid heat, spark, open flames and other sources of ignition.
discharge, shock or vibration	, , , ,

Hazardous decomposition products........ Acetic acid. Carbon dioxide. Carbon monoxide.

SECTION 11: TOXICOLOGICAL INFORMATION

INGREDIENTS		C50	LD50
Homopolymer of HDI	39	00-453 mg/m3 rat 4 hours	> 5,000 mg/kg (rat, oral); > 5,000 mg/kg (rabbit, dermal)
tert-Butyl acetate	>2	2,230 mg/m3 4 hours rat	4,100 mg/kg (rat, oral); >2,000 mg/kg (rabbit, dermal)
Acetic acid, methyl ester	16	6000 ppm(Rat)4 h	LD50 5001 mg/kg (oral rat) LD50 5001 mg/kg (dermal rabbit)
Route of exposure	 Eye contact. Skin contact. Inhalation. Ingestion. ATEmix - TBAC 22 mg/L (inhalation) 4 hour vapour. ATEmix - 9756 mg/L (inhalation) vapour (diisocyanate). Causes serious eye irritation. Causes skin irritation. Solvents may degrease the skin. No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC or ACGIH. No component of this product present at levels greater than or equal to 0.1%. No component of this product present at levels greater than or equal to 0.1%. May cause allergy or asthma symptoms or breathing difficulties if inhaled. May cause an allergic skin reaction. 		or equal to 0.1% is identified ARC or ACGIH. or equal to 0.1% . or equal to 0.1% . ties if inhaled.

SECTION 12: ECOLOGICAL INFORMATION

Ecotoxicity	Do not allow product to enter drains, sewers, bodies of water or soil.
Mobility in soil	Product data not available.
Persistence and degradability	Product data not available.

SECTION 13: DISPOSAL CONSIDERATIONS

and methods of disposal, including any contaminated packaging

Information on safe handling for disposal . Dispose of waste in accordance with all applicable Federal, Provincial/State and local regulations. Empty containers must be handled with care due to product residue.

SECTION 14: TRANSPORT INFORMATION

TDG Classification	UN1263 - PAINT RELATED MATERIAL - Class 3 - Packing Group II - This product meets the Limited Quantity exemption when packaged in containers less than 5 liters.
DOT Classification (Road)	the Limited Quantity exemption when packaged in containers less than 5 liters. UN1263 - PAINT RELATED MATERIAL - Class 3 - Packing Group II - Ltd Qty (5 L).
	Refer to 49CRF 172.101 for additional non-bulk packaging requirement.
IATA Classification (Air)	UN1263 - PAINT RELATED MATERIAL - Class 3 - Packing Group II. Limited Quantity. Do not ship by air without checking appropriate IATA regulations.
	not ship by air without checking appropriate IATA regulations.
IMDG Classification (Marine)	UN1263 - PAINT RELATED MATERIAL - Class 3 - Packing Group II - EmS: F-E S-E.
	Limited Quantity. Check IMDG regulations for limited quantity exemptions.
Marine Pollutant	No.

PRODUCT: 12376 FAST ACTIVATOR FOR 12370

SECTION 14: TRANSPORT INFORMATION

In accordance with Part 2.2.1 of the Transportation of Dangerous Goods Regulations (July Proof of Classification..... 2, 2014) - we certify that classification of this product is correct. .

SECTION 15: REGULATORY INFORMATION

CEPA status..... On Domestic Substances List (DSL).

National Pollutant Release Inventory (NPRI)None listed in this product. Environmental Emergency Regulations.... None listed in this product. Categorization of the DSL..... None listed in this product.

(CAS # 540-88-5). New Substances Risk Assessment

Summary

TSCA inventory status..... All components are listed.

This product is considered hazardous under the OSHA Hazard Communication Standard. OSHA.....

SARA Title III

Section 302 - extremely hazardous None.

substances

Section 311/312 - hazard categories...... Immediate health, delayed health, fire hazard.

Section 313..... EPA hazardous air pollutants (HAPS)

None above De minimus % limit. Hexamethylene diisocyanate.

40CFR63 California Proposition 65.....

This product does not contain any chemical(s) known to the State of California to cause cancer or reproductive toxicity. For more information, go to www.P65Warnings.ca.gov.

SECTION 16: OTHER INFORMATION

REGULATORY AFFAIRS. Prepared by:

(800) 387-7981. Telephone number:.....

DISCLAIMER: All information appearing herein is based upon data obtained from experience and recognized technical sources. To the best of our knowledge, it is believed to be correct as of the date of issue but we make no representations as to its accuracy or Disclaimer:.... sufficiency and do not suggest or guarantee that any hazards listed herein are the only

ones which exist. The hazard information contained herein is offered solely for the consideration of the user, subject to his own investigation and verification of compliance with applicable regulations, including the safe use of the product under every foreseeable condition. The information relates only to the product designated herein, and does not

relate to its use in combination with any other material or in any other process.

2022-11-30. 2024-05-07 Date of the latest revision of the safety

data sheet



Pro Form Products Ltd. 604 McGeachie Drive Milton, Ontario, L9T 3Y5 Canada 905-878-4990

PRODUCT: PB 3001-4 EXTRA CUT COMPOUND

SECTION 01: IDENTIFICATION

Initial supplier identifier..... Pro Form Products Ltd. 604 McGeachie Drive

Milton, Ontario L9T3Y5 Tel (905) 878-4990 Fax (905) 878-1189 PB 3001-4 EXTRA CUT COMPOUND

Product identifier..... Recommended use and restrictions on .. Compound.

Chemical family.....

Mixture. Health: 2 Fire: 2 Reactivity: 0.

NFPA rating.... HMIS..... H: 2 F: 2 R: 0.

For transportation emergencies (in Canada) call CANUTEC 1-888-226-8832 (CAN-UTEC); IN THE UNITED STATES CALL CHEMTREC 1-800-424-9300.

** For medical emergencies contact your local poison control centre **. 24 hour emergency number:....

SECTION 02: HAZARD IDENTIFICATION



Signal Word	DANGER.
Hazard Classification	Flammable Liquid 3. Aspiration Toxicity 1. Skin Irritation — Category 2. Eye Irritation —
	Category 2A. Specific Target Organ Toxicity — Repeated Exposure — Category 1. Health
Hazard Description	Hazard Not Otherwise Classified 1. Causes serious damage to the respiratory tract. H226 Flammable liquid and vapour. H304 May be fatal if swallowed and enters airways.
riazaru Description	H315 Causes skin irritation. H319 Causes serious eye irritation. H372 Causes damage to
	organs through prolonged or repeated exposure.
Prevention	P210 Keep away from heat, sparks, open flames and hot surfaces. No smoking. P233
	Keep container tightly closed. P240 Ground and bond container and receiving equipment.
	P241 Use explosion proof equipment. P242 Use only non-sparking tools. P243 Take
	precautionary measures against static discharge. P260 Do not breathe mist, vapours, or
	spray. P264 Wash thoroughly after handling. P270 Do not eat drink or smoke while using
Deemana	this product. P280 Wear protective gloves and eye protection.
Response	P370 + P378 In case of fire - use dry chemical powder, CO2 or foam to extinguish. P303 + P361 + P353 If on skin or in hair: take off all contaminated clothing immediately. Rinse
	thoroughly with water and use safety shower . P301 + P310 If swallowed IMMEDIATELY
	CALL A POISON CONTROL CENTRE and follow instructions provided by the centre. P331
	Do NOT induce vomiting. P302 + P352 - If on skin: wash with plenty of water. P332 + P313
	- If skin irritation occurs get medical attention or advice. P362 + P364 - Take off
	contaminated clothing and wash before reuse. P305 + P351 + P338 If in eyes rinse
	cautiously with water for several minutes. Remove contact lenses, if present and easy to
	do. Continue rinsing until medical help arrives. P337 + P313 - If eye irritation persists get
	medical attention. P314 - Get medical advice/attention if you feel unwell.
Disposal	P501 Dispose all unused, waste or empty containers in accordance with local regulations.
Note	This product mixture has been classified based on its ingredients.

SECTION 03: COMPOSITION / INFORMATION ON INGREDIENTS				
CHEMICAL NAME AND SYNONYMS	CAS#	WT. %		
Naphtha (petroleum), heavy alkylate	64741-65-7	7-13		
Distillates (Petroleum) Hydrotreated Light	64742-47-8	7-13		
Propylene glycol monobutyl ether	5131-66-8	1-5		
Monoethanolamine	141-43-5	1-5		
The patival approximation (a) with health as a trade popular.				

<<The actual concentration(s) withheld as a trade secret>> .



SECTION 04: FIRST-AID MEASURES

Eye contact	In case of contact, immediately flush eyes, keeping eyelids open, with plenty of water for at least 15 minutes. Obtain medical attention.
Skin contact	Remove all contaminated clothing and immediately wash the exposed areas with copious amounts of water for a minimum of 30 minutes or up to 60 minutes for critical body areas. If
Inhalation	irritation persists, seek medical attention. If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen, obtain medical attention.
Ingestion	If ingestion is suspected, contact physician or poison control center immediately. Do not induce vomiting. If spontaneous vomiting occurs have victim lean forward with head down
	to prevent aspiration of fluid into the lungs. Never give anything by mouth to an unconscious person.
Most important symptoms and effects, whether acute or delayed	
	blurred vision. Direct contact with eyes may cause temporary irritation. Can cause skin
Additional information	sensitization. Causes damage to organs through prolonged or repeated exposure. Treat victims symptomatically. The main hazard from ingestion is aspiration of the liquid into the lungs producing chemical pneumonitis. In the event of an incident involving this
	product ensure that medical authorities are provided a copy of this safety data sheet.

SECTION 05: FIRE-FIGHTING MEASURES

"Alcohol" foam, CO2, dry chemical. In cases of larger fires, water spray should be used. Do not use water in a jet.

Oxides of carbon (CO, CO2). Other potentially toxic fumes.

Firefighter should be equipped with self-contained breathing apparatus and full protective clothing to protect against potentially toxic and irritating fumes. Cool fire-exposed containers with cold water spray. Heat will cause pressure buildup and may cause explosive rupture. Heat will cause pressure buildup and may cause explosive rupture. Keep run-off water from entering sewers and other waterways. Dike for water control. Vapours may be heavier than air. May travel long distances along the ground before igniting and flashing back to vapour source.

Unusual fire / explosion hazards.....

SECTION 06: ACCIDENTAL RELEASE MEASURES

Leak/spill.....

Ventilate. Eliminate all sources of ignition. Avoid all personal contact. Evacuate all non-essential personnel. Contain the spill. Prevent runoff into drains, sewers, and other waterways. Remove all possible sources of ignition in the surrounding area. Use explosion-proof or hand pumps and non-sparking tools and equipment. Absorb with an inert dry material and place in an appropriate waste container. Spilled material and water rinses are classified as chemical waste, and must be disposed of in accordance with current local, provincial, state, and federal regulations.

SECTION 07: HANDLING AND STORAGE

Precautions for safe handling.....

Keep away from heat, sparks, and open flame. This material is a static accumulator. Prevent accumulation of electrostatic charges. Always adopt precautionary measures against build-up of static which may arise from appliances, handling and the containers in which product is packed. Ground handling equipment. Avoid all skin contact and ventilate adequately, otherwise wear an appropriate breathing apparatus. Avoid breathing vapours or mist. Handle and open container with care. Employees should wash hands and face before eating or drinking.

Conditions for safe storage, including any incompatibilities

Keep away from heat, sparks, and open flames. Keep container closed when not in use. Store away from oxidizing and reducing materials. Store away from sunlight.

SECTION 08: EXPOSURE CONTROLS / PERSONAL PROTECTION

INGREDIENTS	TWA	GIH TLV STEL	OS PEL	HA PEL STEL	NIOSH REL
Naphtha (petroleum), heavy alkylate	525 mg/m3	Not established	Not established	Not established	Not established
Distillates (Petroleum) Hydrotreated Light	1200 mg/m3	197 ppm	Not established	Not established	Not established
	CA BC: 200mg/m3	3 (TWA) Skin			
Propylene glycol monobutyl ether	Not Established				



SECTION 08: EXPOSURE CONTROLS / PERSONAL PROTECTION

TWA	CGIH TLV STEL	OS PEL	HA PEL STEL	NIOSH REL
3 ppm	Local exhaust ventilation is when contaminant levels a Liquid chemical goggles. Cexists. Chemical resistant gloves. Wear adequate protective Safety boots per local regulation and face befor Provide natural or mechanexposure limits. Local mecontamination, such as opgases and fumes that may	exceed the recommon chemical safety god chemical safety god chemical safety god chemical ventilation to chanical exhaust ventilation to chemical exhaust ventilation e	ended exposure limits. ggles and full faceshield in the second of the se	f a splash hazard bloyees should wash s. elow airborne at sources of air erations, to capture garding industrial
	TWA 3 ppm	3 ppm 6 ppm Local exhaust ventilation i when contaminant levels exists. Chemical resistant gloves Wear adequate protective Safety boots per local region Emergency showers and their hands and face before Provide natural or mechan exposure limits. Local mecontamination, such as opgases and fumes that may	TWA STEL PEL 3 ppm 6 ppm Not Established Local exhaust ventilation is recommended. We when contaminant levels exceed the recommended. Liquid chemical goggles. Chemical safety goggetists. Chemical resistant gloves. Wear adequate protective clothes. Safety boots per local regulations. Emergency showers and eye wash stations so their hands and face before eating, drinking, or provide natural or mechanical ventilation to dexposure limits. Local mechanical exhaust vecontamination, such as open process equipments gases and fumes that may be emitted. Standoventilation (ie. ACGIH industrial ventilation) significant contamination in the contamination of the contamination in the contamination is significant.	TWA STEL PEL STEL 3 ppm 6 ppm Not Established Not Established Local exhaust ventilation is recommended. Wear an appropriate, prop when contaminant levels exceed the recommended exposure limits. Liquid chemical goggles. Chemical safety goggles and full faceshield in exists. Chemical resistant gloves. Wear adequate protective clothes. Safety boots per local regulations. Emergency showers and eye wash stations should be available. Emptheir hands and face before eating, drinking, or using tobacco products. Provide natural or mechanical ventilation to control exposure levels be exposure limits. Local mechanical exhaust ventilation should be used contamination, such as open process equipment, or during purging op gases and fumes that may be emitted. Standard reference sources reventilation (ie. ACGIH industrial ventilation) should be consulted for gu

SECTION 09: PHYSICAL AND CHEMICAL PROPERTIES

Appearance/Physical stateColour	Liquid. Milky white.
Odour	Weak petroleum hydrocarbon.
Odour threshold (ppm)	Not available.
Vapour pressure (mm Hg)	No data.
Vapour density (air=1)	>1. 7.0 - 9.0.
Relative Density (Specific Gravity)	7.6 lbs/USD - 0.910.
Melting / Freezing point (deg C)	< 0 °C.
Solubility	Water dilutable.
Initial boiling point / boiling range (deg C).	> 100° C.
Evaporation rate	<1. 56. (Closed Cup).
Flash point (deg C), methodAuto ignition temperature (deg C)	246C.
Upper flammable limit (% vol)	23.5.
Lower flammable limit (% vol)	0.5.
Partition coefficient — n-octanol/water	Not available.
VOC (less water) Viscosity	1.68 lbs/USG. 1932 cps Spindle #4.
v 130031ty	1902 cps opinale #4.

SECTION 10: STABILITY AND REACTIVITY

Chemical stabilityReactivity	Stable at normal temperatures and pressures. Avoid heat, sparks and flames. Explosive reactions can occur in the presence of strong
	oxidizing agents. Heating above 60°C in the presence of aluminum can result in corrosion
	and generation of flammable hydrogen gas
Possibility of hazardous reactions	Hazardous polymerization will not occur.
Conditions to avoid, including static	Keep away from heat. Incompatible with strong oxidizers.
discharge, shock or vibration	
	Oxides of carbon (CO.CO2). Thermal decomposition may release acrolein. Does not

Oxides of carbon (CO,CO2). Thermal decomposition may release acrolein. Does not decompose up to 204°C (400°F).

SECTION 11: TOXICOLOGICAL INFORMATION

INGREDIENTS	LC50	LD50		
Naphtha (petroleum), heavy alkylate	>4000 mg/kg dermal rat	>8000 mg/kg oral rat		
Distillates (Petroleum) Hydrotreated Light	>5.2 mg/L (4 hr.)	>5000 mg/kg (oral, rat), >2000 mg/kg (dermal, rabbit)		
Propylene glycol monobutyl ether	>651 ppm 4 Hr Rat	2,700 mg/kg Rat Oral >2,000 mg/kg Rat Skin		
Monoethanolamine	232 ppm Guinea Pig	1720 mg/kg Rat Oral 1018 mg/kg Rabbit Dermal		
Route of exposure Eye contact. Skin contact. Inhalation.				

SECTION 11: TOXICOLOGICAL INFORMATION

The aromatic hydrocarbon solvents in this product can be irritating to the eyes, nose and Effects of acute exposure..... throat. In high concentration, they may cause central nervous system depression and

narcosis characterized by nausea, lightheadedness and dizziness from overexposure by inhalation. May be harmful if absorbed through the skin.

Effects of chronic exposure..... Breathing high concentrations of vapour may cause anesthetic effects and serious health effects. Prolonged or repeated skin contact may cause drying or cracking of skin.

No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC or ACGIH. Carcinogenicity of material.....

Reproductive effects..... No known reproductive effects.

Sensitizing capability of material..... May cause sensitization by skin contact.

Causes damage to organs through prolonged or repeated exposure . Specific Target Organ Toxicity

SECTION 12: ECOLOGICAL INFORMATION

Environmental..... Do not allow to enter waters, waste water or soil. Persistence and degradability..... Not available.

SECTION 13: DISPOSAL CONSIDERATIONS

Information on safe handling for disposal. and methods of disposal, including any contaminated packaging

Dispose of waste in accordance with all applicable Federal. Provincial/State and local regulations.

SECTION 14: TRANSPORT INFORMATION

TDG Classification..... UN1993 - FLAMMABLE LIQUIDS, N.O.S. (Petroleum distillate) - Class 3 - Packing Group III - This product meets limited quantity exemption when shipped in containers less than 5

litres

UN1993 - FLAMMABLE LIQUID, N.O.S. (Petroleum distillates) - Class 3 - PGIII - Ltd Qty (5 DOT Classification (Road)..... Liters/1.3 Gallons)

IATA Classification (Air)..... UN1993 - FLAMMABLE LIQUIDS, N.O.S. (Petroleum distillates) - Class 3 - Packing Group III. Limited Quantity. Do not ship by air without checking appropriate IATA regulations. IMDG Classification (Marine).....

UN1993 - FLAMMABLE LIQUIDS, N.O.S. (Solvent naphtha) - Class 3 - Packing Group III . EmS: F-E, S-E. Limited Quantity. Check IMDG regulations for limited quantity

exemptions.

Marine Pollutant..... Nο

Proof of Classification..... In accordance with Part 2.2.1 of the Transportation of Dangerous Goods Regulations (July

2, 2014) - we certify that classification of this product is correct. .

SECTION 15: REGULATORY INFORMATION

On DSL, or exempt. CEPA status.....

TSCA inventory status..... All components are either listed or exempt from the TSCA. .

This product is considered hazardous under the OSHA Hazard Communication Standard.

SARA Title III

California Proposition 65.....

Section 302 - extremely hazardous None.

substances

Section 311/312 - hazard categories....... Immediate health, delayed health, fire hazard.

Section 313......

EPA hazardous air pollutants (HAPS)

Aluminum Oxide (fibrous forms only).
Methylene Chloride (Dichloromethane). 1,3-Dichloropropene. 40CFR63

> *** ! WARNING: This product can expose you to chemicals including [see below], which are known to the State of California to cause cancer. (Dichloroprene). (Ethyl acrylate). (Methylene chloride). For more information, go to www.P65Warnings.ca.gov.

SECTION 16: OTHER INFORMATION

Prepared by: REGULATORY AFFAIRS. Trivalent Data Systems Ltd. www.trivalent.com. (800) 387-7981.

Telephone number:..... Disclaimer:.....

DISCLAIMER: All information appearing herein is based upon data obtained from experience and recognized technical sources. To the best of our knowledge, it is believed to be correct as of the date of issue but we make no representations as to its accuracy or sufficiency and do not suggest or guarantee that any hazards listed herein are the only ones which exist. The hazard information contained herein is offered solely for the consideration of the user, subject to his own investigation and verification of compliance with applicable regulations, including the safe use of the product under every foreseeable condition. The information relates only to the product designated herein, and does not relate to its use in combination with any other material or in any other process.

2022-11-30. Review Date:....



SECTION 16: OTHER INFORMATION

Date of the latest revision of the safety .. 2018-07-12 data sheet

